


## QUALITY CARGO CONTROL TIEDOWN REFERENCE CARD

*Minimum # of Quality Cargo Control tiedowns required to secure an article against movement based on D.O.T. weight only requirements & C.V.S.A. guidelines.*

		Weight of Load (LBS.)									
		"k" = multiple of thousand									
		5k	10k	15k	20k	25k	30k	35k	40k	45k	50k
<b>Size / Working Load Limit</b>	<b>2" / 3,000 LBS.</b>	1	2	3	4	5	5	6	7	8	9
	<b>2" / 3,335 LBS.</b>	1	2	3	3	4	5	6	6	7	8
	<b>3" / 4,000 LBS.</b>	1	2	2	3	4	4	5	5	6	7
	<b>3" / 5,000 LBS.</b>	1	1	2	2	3	3	4	4	5	5
	<b>4" / 5,000 LBS.</b>	1	1	2	2	3	3	4	4	5	5

*D.O.T. requirements & C.V.S.A. guidelines state that the aggregate working load limit (W.L.L.) of the tiedown assemblies used to secure an article against movement must be at least 1/2 (.5) times the weight of the article.*

*Additional tiedown assemblies may be required to meet industry, local, state & federal regulations.*

**WARNING: DO NOT EXCEED WORKING LOAD LIMITS. (W.L.L.)**  
**DO NOT USE TIEDOWN STRAPS FOR OVERHEAD LIFTING.**